



GPC # Life Beneath Pavers, Operating Furnaces for Years after Glass Breaches

Mohit Gohel
PaneraTech, Inc., United States

Extending Furnace Life Through Early Detection & Data-Driven Action



Radar detection spots refractory wear and glass penetration 2-3 years before temperature increases, enabling proactive cost-saving maintenance.



Polaris™ analytics outperform temperature readings, revealing true wear to optimize cooling, improve furnace operation and extend asset life.



Data-driven actions - precise cooling and timely repairs - extend furnace life by 5 to 6 years even after glass has penetrated to the bottom insulation.

Preview

Insights from 550+ furnace inspections and over 2 million refractory data points reveal: **Traditional methods are not enough to predict refractory maintenance.**

Unreliable as well as late Indicators
for
Refractory Maintenance Decisions



Elevated
temperatures
≠
early warning



Visual
inspections
miss hidden
damage



Gut instinct
leads to
incorrect
actions



**Radar
detects
issues
years
earlier**

Glass Penetration Detection: Temperature Is a Late Indicator

Temperature disguised due to insulation layers

Relying on temperature = late-stage detection.

Radar detects issues 2-3 years earlier.

Early detection = lower costs + longer furnace life.




Surface Temperature Isn't Reliable

Why It Matters: Surface temperature increase after damage; radar detects risks early for proactive maintenance.


Customer Goal: Extend furnace life safely by catching risks early.

Challenge: A hot spot at the furnace bottom **raised** concerns about structural integrity and a possible glass leak.

PaneraTech Technology Insight: Radar finds bottom thinning months or even years before temperature increases.



Temperature is a late Indicator



Radar detects refractory loss years before surface temperature shows any sign.

- Surface temperature is not a reliable indicator due to multi-layer insulation.
- By the time insulation temperature rises, it's too late to act and asset loss is certain.
- Radar identifies issues 2-3 years earlier than traditional inspection methods.

Cold face Surface Temperature (Degree C)	Refractory Thickness (mm)
136	286
145	454
128	610


Temperature is a late Indicator for Metal Penetration

Glass Type: **Green** Cullet: **50%** Furnace Size: **141 m²**

No Correlation between Temperature and Metal penetration depth.

Cold face Surface Temperature (Degree C)	Remaining Insulation Thickness with metal (mm)
--	--

154	484
208	501
219	565



Extended Asset Life with Data Driven Decision


Glass Type: **Green** Cullet: **50%** Furnace Size: **141 m²**

Findings: **39%** of total bottom blocks are having metal at the bottom

Furnace ran nearly **3 years** without hot bottom repair.


Repair performed **after 3 years** from metal penetration found into insulation.

Furnace is still in operation



Why Temperature Fails for Glass Leak Risk Monitoring


Delayed Indication



Poor Correlation between Temperature and Bottom Thickness



Hidden Infiltration and Insulation Loss



Molten glass above the bottom refractory can silently infiltrate and erode insulation beneath, without any visible surface signs. This hidden damage spreads horizontally, undermining furnace integrity while surface temperature appears normal.



Learning from the Float Furnace Bottom Monitoring



Learning from the Float Furnace Bottom Monitoring

Objective: At what bottom condition the **industry initiates** SmartMelter® float bottom assessment

Facts about the data


- **Data Period:** Sept. 2016-Oct. 2024
- **First time** furnace is visited-**minimum** observed **bottom thickness**
- **22** Float Manufacturers
- **80** Furnaces
- Geographically in the US, Europe, Middle East, South America, Africa and Asia

Risk Categories



Furnace Bottom Condition at First SmartMelter® Assessment

Float Manufacturer



KEY OBSERVATION


Furnaces with glass into clay flux

Data shows almost 20% of the furnaces come to us when glass is already below the pavers.

Chart shows glass infiltration into the Insulation and insulation residual thickness in mm

Maintenance Methods

Grating



Maintenance methods
chosen based on **thickness**
criticality and **desired**
furnace life extension


Grating + Air Cooling



Grating + Water Cooling



AZS chips repair




Drilled Holes



Furnace Life Extension (Months) & Maintenance Type

Extended Furnace Life & Clay flux remaining Thickness (Months & mm)



- Extensions of ≤ 5 months involved bottom issues and other operational concerns too.
- Large circles: Furnace is in operation currently.
- Small circles: Furnace shut down safely as per no. of months mentioned in chart.
- Different Colour Codes: Indicate maintenance type following glass infiltration into insulation.

Type of Maintenance

No Actions



Air Cooling



AZS Chips repair




Air + Water Cooling




Early Detection Helps with Slowing Wear

First radar mapping




201 mm
(8in)


2nd radar mapping
+10 months



3rd radar mapping
+16 months



Final radar mapping
+22 months



156 mm
(6.25in)

This furnace was monitored over 22 months.

- After nearly two years, the thinnest spot only eroded 50 mm.
- The affected area of the clay flux increased by 5 times since the first mapping.
- Air cooling was applied on the outside surface based on areas identified by 3D mapping.

Asset Life Extension on a Float Bottom

Campaign Start Date: 2008,

Expected Campaign End Date: 2027

2021: Gratings & air + water cooling added

Regular Follow-up inspections


No hot repairs.

Furnace life was extended by four years and
expected life increase up to six years.


Reduced wear rates,

Minimized firefighting maintenance, and

Ensured optimal glass pull stability.




Timely and precise actions control wear rate effectively




Follow Up Inspection Results

2021



- Targeted air- & water-cooling kept wear rates below 1.5 mm/month for 3.5+ years, ensuring safe furnace operation until 2025 scheduled repair.

2024



Asset Life Extension in a Float Bottom

Customer implemented grating support, applied air cooling, managed wear rates, and coordinated timely AZS chip repairs.


Furnace life was extended by nearly two years.

Reduced wear rates,
Minimized reactive maintenance, and
Ensured optimal glass pull stability.

Wear rate change depends on action effectiveness..


Inspection and Repair Activity Timeline:

- Campaign Start Date: 2009
- 2019: Limited Scope of Bottom Inspection - No wear observed
- 2022: Wear identified in clay flux
- 2023 & 2024: Hot bottom AZS chip repairs with defined scope
- Regular Follow-ups: 7 Inspections from 2022 to 2024



Glass Into clay flux

2022




2024



Early Glass Penetration Detection Saves Furnace


Traditional Cooling

Following Traditional Cooling - Wear rate is high and lost almost 46 mm in 6 months.



Aggressive Cooling

Aggressive & Focused Cooling - Wear rate under control and lost only 6 mm in 6 month.




Maintenance & Expected Furnace Life Extension

Glass into Clay flux - Maintenance & Expected Furnace Life Extension


Type of Maintenance	Cost Associated with Maintenance	Pros - Cons	Expected Increase of lifetime
No Maintenance - Just Visual & Thermal Observation	No Additional Cost	Only monitoring, risk management	0 - 1 year for clear glass
Low Maintenance	<10K US\$	Stoppage of bubblers (It could affect production)	0 - 1 years
		Reduce boosting (It could affect production)	
		Add grating to support concerned area	
Medium Maintenance	<250K US\$	Cool concerned area by making holes and /or use of air lance and/or use of water	1 - 4 Years
High Maintenance	>1M US\$	Hot bottom repair - using AZS chips	2 - 5 Years
		Hot bottom repair - cast concrete	



Technology: Online thickness monitoring - Polaris™




Control Box



Sensor Network in Furnace Bottom



Sensor at Metal Line



**Furnace Bottom Area Continuously
Monitored**

Description:

Polaris™ IoT Refractory Sensor System: Permanent sensor enables continuous real-time radar monitoring of refractory thickness in high-risk areas—sidewall, bottom, and throat.

Why it Matters?

1. Real-time Feedback on Impact of Furnace Operations on Refractory Life
2. Risk Management for Bottom
3. Benchmark Process History
4. Optimize Quality, Lifespan, and Energy consumption:
Maintain output with less refractory wear


Key Business Outcomes:

- Improved Furnace Life
- Improved Furnace Operations
- Lower Energy Consumption


Asset Life Optimization

Asset life is frequently overlooked by engineers in day-to-day furnace operation.

Corrosion rate doubles for every $\sim \Delta T = 50^{\circ}\text{C}$



Online - Polaris™ Layout Examples & Disclaimer



Polaris™ IoT Refractory Sensor System: Permanent sensor provides continuous real-time radar monitoring of refractory thickness, deeper than portable sensors

Detects through ramming mix up to the cold face of the paving.

Advantages

1. Real-time feedback on furnace operation impact on refractory life (e.g., metal infiltration, wear).
2. Deeper visibility due to continuous data
3. Wear rate can be tracked and compared with operational changes.
4. Coverage can be achieved 80 - 90% of the bottom.








Note: Red circle in bottom layout show Polaris coverage.

Online Wear Analysis on an Operational Furnace


Furnace process data from July 2024 to January 2025

- I. **Green glass** at about 100% pull
- II. **Clear glass** at about 100% pull and **90°C increase** in temperature from **Period I**
- III. **Clear glass** at about 80% - 90% pull and **80°C increase** in temperature from **Period I**

Left sidewall sensor



AZS Residual Thickness Over Time




Leveraging Online Thickness Data: Uneven Wear


Severe left-side wear discovered with refractory thickness monitoring

Cause: Imbalanced sidewall cooling and imbalanced internal temperature


Actions: Cooling improvement and temperature optimization following optical temperature



Metal line residual thicknesses in mm



+40 Degree C Temperature at left side of the furnace



Lesser cooling at left sidewall

Leveraging Online Thickness Data: Uneven Wear




Moderate downstream and upstream **wear imbalance** discovered in Polaris™ data

Equal and **adequate** sidewall cooling on both sides was found

Batch piles found to be progressing far downstream and against left side, **causing higher wear**

Residual thickness mm

Current wear rates mm/month



Conclusion



Traditional indicators such as temperatures are not enough



Early detection = Cost savings + Operational stability



Polaris™ data empowers actionable insights



Real-world results: Up to 6 years of life extension

Temperature Papers



Download our Paper:
Temperature Part 1
*An Unreliable Indicator of
Refractory Wear*



Download our Paper:
Temperature Part 2
*A Late Indicator of Glass
Penetration*



Mohit Gohel

mohit.gohel@paneratech.com

4035 Ridge Top Road
Suite 510
Fairfax, VA 22030 USA
+1 (703) 719-9666
+919727768313

